Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: REDMOND 1-06H

Field Name: CLEAR WATER Well File #: 18449

Date Incident:5/24/2016Time Incident:09:30Facility ID Number:County:MOUNTRAILTwp:157Rng:89Sec:6Qtr:

Location Description: The ROW off the Redmond 1-06H pad approximately 40 feet to the north of

the tank battery was the source of the leak with PW affecting the surface soils

about 350 'x 3' area to the north.

Submitted By: Danielle Dupay Received By:

Contact Person: Danielle Dupay

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well: Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 5 Barrels 5 Barrels 5 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 8/31/2016 Clean Up Concluded: 6/3/2016

Risk Evaluation:

N/A

Areal Extent:

North 40' ROW off the Redmond 1-06H pad with surface soil contamination 350'x3' to the north

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The line was day lighted to find the source of the leak. The surface contaminated soils were removed and brought on site and have been contained and will be disposed of today. The PW line on the ROW will be opened up for repairs and any other contaminated soils will be removed and disposed of.

Wastes Disposal Location: Clean Harbors, Sawyer ND

Agencies Involved:

Updates

Date: 5/27/2016 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release on pipeline ROW. Follow-up is required.

Date: 6/1/2016 Status: Inspection Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 13:20. 59 degrees F, sunny, NW wind 10-20 mph. Walked the area and took photos. It appeared the cleanup was still in progress, but yet on hold due to heavy precipitation earlier. It appeared that the release occurred north of the well pad in a cultivated field. It appeared that the release surfaced and moved to the west then south towards a wetland west of the well pad. Water samples were collected and tested for chlorides in 3 locations. Chloride strip samples showed chlorides below the lowest range, <31 ppm. Soil confirmation sample analytical and water sample analytical should be documented for this release. More followup needed.

Date: 6/8/2016 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12:15 6/8/2016.

Fresh turned soil was in the area that had been affected, with no signs of residual contamination. Cleanup appears complete.

No followup necessary.